



Instructions

48oz Pump Up Foam Sprayer used for Application
Of Aluminum & Metal Cleaner/Brightener

NOTE: READ ALL WARNINGS PRIOR TO APPLICATION. WEAR APPROPRIATE PERSONAL PROTECTIVE EQUIPMENT - READ MSDS

1. Attach white foam tip to spray nozzle (if not attached)
2. Fill container to 1.5lt mark with product.
3. Pump Foam Sprayer 15-20 times
4. Wet surface under area to be treated (floors, driveways, etc.)
5. Adjust foam consistency by twisting the spray nozzle
6. Apply foam generously to surface to be treated. Note: The surface to be treated should be dry prior to application. Only foam an area which can be worked in less than 10 minutes. Do not allow product to dwell on surface for extended periods of time.
7. Gently agitate foam with a Shield Solutions™ soft bristle brush. Take care not to splash product.
8. THOROUGHLY RINSE treated and surrounding area as well as the floor/ground with cold water to dilute and remove any remaining product. Dry treated area. Note: It is recommended that the vehicle be washed with Shield Solutions™ Vehicle Wash upon completion of aluminum and metal cleaning.
9. Repeat process if necessary to achieve the desired effect.
10. Empty and clean Foam Sprayer after each use. DO NOT LEAVE PRODUCT IN SPRAYER.

Shield Solutions, LLC

W1737 Washington Rd | Oconomowoc, WI 53066 USA | 920-474-7502 ~ 877-474-7497

www.shieldsolutionsllc.com

Revision 5/5/2011



Instructions

48oz Pump Up Foam Sprayer used for Application
Of Aluminum & Metal Cleaner/Brightener

NOTE: READ ALL WARNINGS PRIOR TO APPLICATION. WEAR APPROPRIATE PERSONAL PROTECTIVE EQUIPMENT - READ MSDS

1. Attach white foam tip to spray nozzle (if not attached)
2. Fill container to 1.5lt mark with product.
3. Pump Foam Sprayer 15-20 times
4. Wet surface under area to be treated (floors, driveways, etc.)
5. Adjust foam consistency by twisting the spray nozzle
6. Apply foam generously to surface to be treated. Note: The surface to be treated should be dry prior to application. Only foam an area which can be worked in less than 10 minutes. Do not allow product to dwell on surface for extended periods of time.
7. Gently agitate foam with a Shield Solutions™ soft bristle brush. Take care not to splash product.
8. THOROUGHLY RINSE treated and surrounding area as well as the floor/ground with cold water to dilute and remove any remaining product. Dry treated area. Note: It is recommended that the vehicle be washed with Shield Solutions™ Vehicle Wash upon completion of aluminum and metal cleaning.
9. Repeat process if necessary to achieve the desired effect.
10. Empty and clean Foam Sprayer after each use. DO NOT LEAVE PRODUCT IN SPRAYER.

Shield Solutions, LLC

W1737 Washington Rd | Oconomowoc, WI 53066 USA | 920-474-7502 ~ 877-474-7497

www.shieldsolutionsllc.com

Revision 5/5/2011